Frost Productions

Clay Paky
Glow Up C Settings

Power Up

Press   and Hold **S**

Set up as Master
                From Home Screen

Press	**E** twice
Press	**Down** Until Display Reads **Master/Slave**
Press	**E**
Press	**Down** Until Display reads **Transmitter**
Press	**E**

Set up as Slave (Same Mode for Wireless DMX)

                                   From Home Screen

For Multiple Groups Set up # of slaves then Master and repeat for each Group

Press	**E** twice
Press	**Down** Until Display Reads **Master/Slave**
Press	**E**
Press	**Down** Until Display reads **Receiver**
Press	**E**

Set up as Stand Alone Mode
                From Home Screen

Press	**E** twice
Press	**Down** Until Display Reads **Stand Alone/DMX**
Press	**E**
Press	**Up twice**
Press	**E** (This will allow you to pick from Preset Colors or set a fixed color)

                To select a Preset color

Press	**E**
Press	**Up** Until **your desired Color (There are 52 to chose from)**
Press	**E**

Frost | Productions

Mix Your Own Color

Press	**Down** Until Arrow is Next To **Red**
Press	**E**
Press	**Up** Until Desired Level is Set
Press	**E**
Press	**Down** Until Arrow is Next To **Green**
Press	**E**
Press	**Up** Until Desired Level is Set
Press	**E**
Press	**Down** Until Arrow is Next To **Blue**
Press	**E**
Press	**Up** Until Desired Level is Set
Press	**E**
Press	**Down** Until Arrow is Next To **White**
Press	**E**
Press	**Up** Until Desired level is set
Press	**E**

To Change Intensity in Stand Alone

Press	**Down** Until Arrow is Next **Dimmer**
Press	**E**
Press	**Down** Until Desired Level is Set
Press	**E**

Set Strobe

Press	**Down** Until Display Reads **Stop-Strobe**
Press	**E**
Press	**Up** Until Desired Strobe is reached
Press	**E**